

PERFIL U DE CHAPA				
MEDIDA			ESPESOR	KG/MT
80	40		2	2,39
100	50		2	2,95
			2,5	3,69
120	50		2	3,27
			2,5	4,08
			3,2	5,20
140	60		2	3,89
			2,5	4,87
			3,2	6,20
160	60		2	4,21
			2,5	5,26
			3,2	6,71
180	70		2,5	6,08
			3,2	7,71
200	80		2,5	6,87
			3,2	8,72
PERFIL C DE CHAPA				
MEDIDA			ESPESOR	KG/MT
80	40	15	1.60	2.22
			2.00	2.76
80	50	15	1.60	2.47
			2.00	3.08
			2.50	3.77
100	40	15	1.60	2.50
			2.00	3.11
100	50	15	1.60	2.73
			2.00	3.39
			2.50	4.16
			3.20	5.17
120	50	15	1.60	2.98
			2.00	3.71
			2.50	4.55
			3.20	5.68
140	60	20	2.00	4.49
			2.50	5.53
			3.20	6.88
160	60	20	2.00	4.80
			2.50	5.93
			3.20	7.44
180	70	20	2.00	5.40
			2.50	6.67
			3.20	8.39
200	80	20	2.00	6.03
			2.50	7.46
			3.20	9.39